| Ref<br>#   | Hits   | Search Query  | DBs   | Default<br>Operator | Plurals | Time Stamp       |
|------------|--------|---|---|---------------------|---------|------------------|
| S1         | 2261   | 219/202,208,205,206.ccls.                             | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR                  | ON      | 2006/11/28 15:03 |
| S2         | 33037  | semiconductor near4 switch                            | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR                  | ON      | 2006/11/29 10:11 |
| <b>S</b> 3 | 13     | S1 and S2   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR                  | ON      | 2006/11/28 15:03 |
| S4         | 0      | ("2005/0173394").URPN.                                | USPAT   | OR                  | ON      | 2006/11/28 15:08 |
| S5         | 127063 | current near4 (detect\$3 or sens\$3)                  | USPAT   | OR                  | ON      | 2006/11/28 16:32 |
| S6         | 4      | S3 and S5   | USPAT   | OR                  | ON      | 2006/11/28 15:10 |
| S7         | 3519   | 219/490,501,504,507,509,510,520,<br>523.ccls.         | USPAT   | OR                  | ON      | 2006/11/28 16:32 |
| S8         | 60     | S2 and S7   | USPAT   | OR                  | ON      | 2006/11/28 15:11 |
| S9         | 260    | 338/226,230,256.ccls.                                 | USPAT   | OR                  | ON      | 2006/11/28 15:26 |
| S10        | 82     | PROFET  | USPAT   | OR                  | ON      | 2006/11/28 16:58 |
| S11        | 10022  | (air same heater) and (vehicle or auto or automobile) | USPAT   | OR                  | ON      | 2006/11/28 17:56 |
| S12        | 43     | S2 and S11  | USPAT   | OR                  | ON      | 2006/11/28 15:45 |
| S14        | 18     | S12 and S5  | USPAT   | OR                  | ON      | 2006/11/28 15:57 |
| S15        | 12529  | resin with frame                                      | USPAT   | OR                  | ON      | 2006/11/28 16:28 |
| S16        | 64     | S11 and S15   | USPAT   | OR                  | ON      | 2006/11/28 16:28 |
| S17        | 0      | S15 and S9  | USPAT   | OR                  | ON      | 2006/11/28 16:28 |
| S18        | 20970  | resin same frame                                      | USPAT   | OR                  | ON      | 2006/11/28 17:55 |
| S19        | 0      | S18 and S9  | USPAT   | OR                  | ON      | 2006/11/28 16:29 |
| S20        | 64     | S15 and S11   | USPAT   | OR                  | ON      | 2006/11/28 16:29 |
| S25        | 883    | 219/552.ccls.   | USPAT   | OR                  | ON      | 2006/11/28 16:32 |
| S26        | 6130   | 219/490,501,504,507,509,510,520,<br>523.ccls.         | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR                  | ON      | 2006/11/28 16:33 |

| S27 | 90             | S26 and S2  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 16:33 |
|-----|----------------|---|---|----|----|------------------|
| S28 | 30             | S27 not S8  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 16:33 |
| S29 | 128            | PROFET  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 16:58 |
| S30 | <del>4</del> 6 | S29 not S10   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 17:07 |
| S31 | 9939           | hidetaka.in.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 17:08 |
| S34 | 14             | ("3748439"   "4032752"   "4053864"   "4368380"   "4414052"   "4482801"   "4588456"   "5192853"   "5235741").PN. OR ("5354969"). URPN. | US-PGPUB;<br>USPAT;<br>USOCR                          | OR | ON | 2006/11/28 17:18 |
| S35 | 890            | 219/546.ccls.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 17:18 |
| S36 | 22             | ("0776491"   "0918732"   "1358059"<br>  "1403330"   "1846233"  <br>"2730609"   "2856494"  <br>"3265865").PN. OR ("3904851").<br>URPN. | US-PGPUB;<br>USPAT;<br>USOCR                          | OR | ON | 2006/11/28 17:52 |
| S37 | 83113          | resin same frame  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 17:55 |
| S38 | 2              | S35 and S37   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 17:55 |

|     |        |   |   | т  |    |                  |
|-----|--------|---|---|----|----|------------------|
| S39 | 158613 | "219"/\$.ccls.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 17:56 |
| S40 | 557    | S37 and S39   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 17:56 |
| S41 | 27876  | (air same heater) and (vehicle or auto or automobile) | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 09:32 |
| S42 | 10     | S40 and S41   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/28 17:56 |
| S43 | 159856 | (air same heater)                                     | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 09:32 |
| S44 | 441    | 123/142.5e.ccls.                                      | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 09:52 |
| S45 | 1334   | 123/142.5r.ccls.                                      | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 09:52 |
| S46 | 1240   | S45 not S44   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 09:53 |
| S47 | 323    | S43 and S46   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 10:11 |
| S48 | 1525   | 219/497.ccls.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 10:11 |

|     | <u> </u> | r                          | <del></del>   | r  | r   |                  |
|-----|----------|----------------------------|---|----|-----|------------------|
| S49 | 219      | S43 and S48                | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON  | 2006/11/29 11:59 |
| S50 | 33037    | semiconductor near4 switch | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON  | 2006/11/29 10:11 |
| S51 | 6        | S49 and S50                | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON  | 2006/11/29 10:16 |
| S52 | 1        | ("20020179443").PN.        | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO             | OR | OFF | 2006/11/29 10:17 |
| S53 | 2        | "07078671"                 | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON  | 2006/11/29 11:59 |
| S54 | 1        | 1995-152459.NRAN.          | DERWENT   | OR | ON  | 2006/11/29 12:13 |
| S55 | 1        | "07217508"                 | DERWENT   | OR | ON  | 2006/11/29 13:07 |
| S56 | 1        | "2000257518"               | DERWENT   | OR | ON  | 2006/11/29 13:43 |
| S57 | 169018   | switch same frame          | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON  | 2006/11/29 13:43 |
| S58 | 3138     | S43 and S57                | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON  | 2006/11/29 13:43 |
| S59 | 158613   | "219"/\$.ccls.             | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON  | 2006/11/29 13:43 |
| S60 | 407      | S58 and S59                | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON  | 2006/11/29 13:44 |

|     |         |   |   | ,  |    |                  |
|-----|---------|---|---|----|----|------------------|
| S61 | 2671784 | (vehicle or auto or automobile)   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 13:44 |
| S62 | 93      | S60 and S61   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 13:47 |
| S63 | 4       | "02019707"  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 13:47 |
| S64 | 8       | ("20010013512"   "20010050843"  <br>"20020011484"   "5461766"  <br>"5596231"   "6046498"   "6545351"<br>  "6700780").PN. OR ("6919535").<br>URPN. | US-PGPUB;<br>USPAT;<br>USOCR                          | OR | ON | 2006/11/29 13:51 |
| S65 | 1       | S57 and S64 .   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 14:40 |
| S66 | 5743    | (overheat\$3 or overtemperature)<br>near2 protect\$4  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 14:41 |
| S67 | 432     | S43 and S66   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 14:41 |
| S68 | 68      | S67 and S59   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON | 2006/11/29 14:41 |
| S69 | 23      | ("4482801").PN. OR ("5057672").<br>URPN.  | US-PGPUB;<br>USPAT;<br>USOCR                          | OR | ON | 2006/11/29 14:46 |
| S71 | 2529008 | protect\$3  | US-PGPUB;<br>USPAT;<br>USOCR;<br>JPO;<br>DERWENT      | OR | ON | 2006/11/29 14:54 |

| S72 | 38     | S70 and S71         | US-PGPUB;<br>USPAT;<br>USOCR;<br>JPO;<br>DERWENT      | OR | ON  | 2006/11/29 15:00 |
|-----|--------|---------------------|---|----|-----|------------------|
| S73 | 1      | ("20010021093").PN. | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO             | OR | OFF | 2006/11/29 17:18 |
| S74 | 0      | ("failure").PN.     | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO             | OR | OFF | 2006/11/29 17:18 |
| S75 | 791413 | failure             | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON  | 2006/11/29 17:18 |
| S77 | 17     | S75 and S76         | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT | OR | ON  | 2006/11/29 17:18 |

11/29/2006 7:26:42 PM C:\Documents and Settings\sralis\My Documents\EAST\Workspaces\10554359.wsp